Message Text

UNCLASSIFIED

PAGE 01 KUWAIT 02571 161506Z

46

ACTION FBOE-00

INFO OCT-01 NEA-10 ISO-00 A-01 SSO-00 /012 W $\,$

----- 056606

O 161400Z JUN 75

FM AMEMBASSY KUWAIT

TO SECSTATE WASHDC IMMEDIATE 3191

UNCLAS KUWAIT 2571

FOR A/FBO AND NEA/EX

E.O. 11652: NA TAGS: ABLD, KU

SUBJ: SWIMMING POOL REPAIR AND OTHER FBO PROJECTS

REF: A. STATE 136892 B. KUWAIT 2494 AND 2496 C. 6FAM 754

- 1. EMBASSY HAS RECEIVED BID FROM CULLIGAN AGENT FOR REPAIR AND MODIFICATION OF SWIMMING POOL AS REQUESTED BY REF A. FOLLOWING IS MINOR IMPREOVEMENT PER REF C.
- 2. PROPERTY DESCRIPTION: SWIMMING POOL IN AMERICAN COMPOUND, KUWAIT. PROPERTY NO. 02445-G.
- 3. PROPOSED REPAIRS/MODIFICATION-REPLACEMENT OF ALL WATER DISTRIBUTION AND LINES, EXCEPT MAIN DRAIN PREVIOUSLY REPLACED, WITH PVC PIPING AND ADDITION OF MORE WATER FEED OUTLETS, SKIMMERS, CHLORINATION, AND 2 NEW PUMPS FOR INCREASED CIRCULATION. REPLACEMENT OF CRACKED AND BROKEN SLIP-PROOF UNCLAZED CERAMIC TILE AROUND IMMEDIATE EDGES OF POOL. RETILING OF ENTIRE MAIN POOL AND NEW TILE ON CEMENT-FINISH CHILDREN'S WADING POOL. RESURFACING OF BALANCE OF CONCRETE DECKING IN BALANCE OF POOL COMPOUND USING PRECAST CONCRETE PAVING BLOCKS WITH GREATLY INCREASED NUMBER OF EXPANSION JOINTS.
- 4. JUSTIFICATIONS: PRESENT POOL WAS BUILT IN 1967. CONSTRUCTION WAS GENERALLY GOOD BUT DESIGN IS STRICKLY AMERICAN AND NOT SUITABLE FOR OPERATION IN SEVERE KUWAIT CLIMATE. POOL LACKS ADEQUATE CIRCULATION CAPACITY, CHLORINE IS NOW ADDED AT POOL UNCLASSIFIED

UNCLASSIFIED

PAGE 02 KUWAIT 02571 161506Z

OUTLET RATHER THAN INLET, INSUFFICIENT EXPANSION JOINT WERE

PUT IN THUS PERMITTING SEVERE CRACKING AND HEAVING OF POOL INTERIOR, SIDES, SLIP PROFF DECKING, AND CONCRETE SLAB COMPOUND DECKS. POOL TILE AND DECKS HAVE DETERIORATED TO POINT THAT FURTHER REPAIR IS NO LONGER POSSIBLE AND POOL IS BEGINNING TO LEAK. METAL WATER DISTRIBUTION LINES HAVE RUSTED TO POINT THAT INTERIOR SECTIONS ARE SHEARING AWAY AND BEING SUCKED INTO PUMPS AND FILTERS. GROWTH OF EMBASSY STAFF HAS INCREASED POOL USAGE TO POINT IT IS NOW A PUBLIC POOL USED HEAVILY AT ALL TIMES FROM APRIL 1 THEOUGH NOV 15. POST IS UNABLE TO MAINTAIN SATISFACTORY SHEMICAL BALANCE TO ENSURE POOL DOES NOT BECOME A HEALTH HAZARD TO SWIMMERS. THIS POOL IS THE SOLE RECREATIONAL FACILITY IN KUWIAT AVAILABLE TO AND USED BY ALL MEMBERS OF THE STAFF. WE FEAR A TOTAL BREAKDOWN IS IMMINENT,. CAUSING LOSE OF WATER, FURTHER DAMAGE TO POOL, AND SEVERE BLOW TO STAFF MORALE.

5. DESCRIPTION OF WORK:

A. LARGE POOL DIMENSIONS: LENGTH 16 METERS, WIDTH 8.90 METERS, DEEP END DEPTH 3.25 METERS, SHALLOW END DEPTH 1.85 METERS, USUAL WATER DEPTH 3.0 METERS AT DEEP END.

- B. SMALL POOL DIMENSIONS: LENGTH 8.9 METERS, WIDTH 5.8 METERS, DEPTH.8 METERS, USUAL WATER DEPTH.5 METERS.
- C. AREA OF SLIP-PROFF UNGLAZED CREAMIC TILE IMMEDIATELY ADJANCENT TO POOLS: $210~\mathrm{SQ}$ METERS.
- D. AREA OF CONCRETE DECKING IN BALANCE OF POOL COMPOUND: 965 SO METERS.
- E. EXISTING WATER DISTRIBUTION LINES AND FEED NOZZELES WILL BE REMOVED AND NUMBER INCREASED FROM 6 TO 12 IN LARGE POOL AND FROM 3 TO 6 IN WADING POOL.
- F. SINGLE SKIMMER IN LARGE POOL WILL BE INCREASED TO 6 SKIMMERS AND 3 SKIMMERS WILL BE PUT IN WADING POOL WHERE NONE NOW EXIST.
- G. CHLORINATORS WILL BE ADDED TO FEED LINES FOR EACH POOL PERMITTING ADDITION OF CHLORINE AT SEPERATE RATES FOR EACH POOL.
- H. VACUUM LINES AND FITTINGS WILL BE REPLACED.
- I. ALL CORRODED GALVANIZED PIPING WILL BE REPLACED WITH PVC PIPING.
- J. TWO NEW CULLIGAN POOLPUMPS WILL BE ADDED TO INCREASE FLOW RATES AND CIRCULATION SPEED THROUGH NEW FILTER PREVIOUSLY UNCLASSIFIED

UNCLASSIFIED

PAGE 03 KUWAIT 02571 161506Z

INSTALLED.

K. MAIN POOL WILL BE COMPLETELY RETILED WITH CERAMIC TILE AND NON-FUNCTIONAL GUTTER REMOVED. NEW COPING WILL BE INSTALLED.

L. WADING POOL WILL BE TILED WITH CERAMIC TILE.

M. NEW SLIP-PROFF UNGLAZED CERAMIC TILE WITH ADDITIONAL EXPANSION JOINTS WILL BE INSTALLED IMMEDIATELY ADJANCENT TO BOTH POOLS.

N. BALANCE OF CONCRETE DECKS WILL BE REPAVED WITH PRECAST

CONCRETE PAVING BLOCKS 60CM SQ. EXPANSION JOINTS BETWEEN BLOCKS WILL ELIMINATE CRACKING AND HEAVING PROBLEMS.

6. ESTIMATE OF COSTS: COSTS ARE LISTED IN ORDER IN WHICH WORK MUST BE ACCOMPLISHED:

A. PLUMBING WORK \$9810.00 RPT \$9810.00
B. TILING OF POOL INTERIOR \$9800.00 RPT \$9800.00
C. PUMPS AND ELECTRICAL \$WTPPMPP RPT \$2500.00
B. SLIP-PROFF UNGLAZED TILING \$6645.00 RPT \$6645.00
E. CONCRETE PAVING BLOCKS \$10.650 RPT \$10.650

7. RELATIVE COSTS BEFORE AND AFTER: PRECISE COSTS SAVING NOT AVAILABLE BUT MAINTENANCE COSTS SHOULD BE SHARPLY REDUCED. ANNUAL REPAINTING OF DECKS AND WADING POOL WILL BE ELIMATED. CHEMICAL CONSUMPTION SHOULD BE REDUCED BY IMPROVED CIRCULATION AND DAILY CLEANING GREATLY SIMPLIFIED. WATER QUALITY WILL BE IMPROVED AND RISK OF BACTERIAL INFESTING REDUCED.

8. NO ADDITIONAL REQUIREMTNS ARE FORSEEN AS A RESULT OF THIS PROJECT.

9. LESSOR'S AGENT HAS INDICATED NO OBJECTION TO THIS PROJECT.

10. IF DEPARTMENT ABLE TO FUND THIS PROJECT, POST IS PREPARED TO OBLIGATE FUNDS PRIOR TO JUNE 30, 1975.

11. IN VIEW OF NUMBER OF FBO PROJECTS SUBMITTED DURING PAST FEW DAYS, POST WISHES TO IDENTIFY PRIORITIES FOR FUNDING.

A. PRIORITY 1: REPLACEMENT OF CEILINGS AND INSULATION IN CHANCERY (KUWAIT OM DATED MAY 3, 1975.)

B. PRIORITY 1: ELECTRICAL REWIRING IN CHANCERY (KUWAIT OM UNCLASSIFIED

UNCLASSIFIED

PAGE 04 KUWAIT 02571 161506Z

DATED MAY 31, 1975 AND KUWAIT 2297)

- C. PRIORITY 2: CONNECTION TO MUNICIPAL SEWER LINES (KUWAIT 2545).
- D. PRIORITY 3: SWIMMING POOL REPAIR (SUBTEL).
- E. PRIORITY 4: WAREHOUSE/WORKSHOP BUILDING (KUWAIT OM DATED JAN 20, 1975 AND MAY 24, 1975).

UNCLASSIFIED

	Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 06 JUL 2006
NNN	
INININ	

Message Attributes

Automatic Decaptioning: X Capture Date: 01 JAN 1994 Channel Indicators: n/a

Current Classification: UNCLASSIFIED

Concepts: n/a Control Number: n/a Copy: SINGLE Draft Date: 16 JUN 1975 Decaption Date: 01 JAN 1960 Decaption Note: Disposition Action: n/a Disposition Approved on Date: Disposition Authority: n/a Disposition Case Number: n/a

Disposition Camment:
Disposition Date: 01 JAN 1960
Disposition Event:
Disposition History: n/a Disposition Reason: Disposition Remarks:

Document Number: 1975KUWAIT02571 Document Source: CORE Document Unique ID: 00

Drafter: n/a Enclosure: n/a Executive Order: N/A Errors: N/A

Film Number: D750209-0169

From: KUWAIT

Handling Restrictions: n/a

Image Path:

Legacy Key: link1975/newtext/t19750647/aaaabqwv.tel Line Count: 164 Locator: TEXT ON-LINE, ON MICROFILM

Office: ACTION FBOE Original Classification: UNCLASSIFIED Original Handling Restrictions: n/a Original Previous Classification: n/a Original Previous Handling Restrictions: n/a

Page Count: 3

Previous Channel Indicators: n/a Previous Classification: n/a Previous Handling Restrictions: n/a

Reference: 75 STATE 136892, 75 KUWAIT 2494, 75 AND 2496, 75 6FAM, 75 754

Review Action: RELEASED, APPROVED Review Authority: greeneet

Review Comment: n/a Review Content Flags: Review Date: 02 DEC 2002

Review Event:

Review Exemptions: n/a
Review History: RELEASED <02 DEC 2002 by PhilliR0>; APPROVED <13 FEB 2004 by greeneet>

Review Markings:

Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 06 JÚL 2006

Review Media Identifier: Review Referrals: n/a Review Release Date: n/a Review Release Event: n/a **Review Transfer Date:** Review Withdrawn Fields: n/a

Secure: OPEN Status: NATIVE

Subject: SWIMMING POOL REPAIR AND OTHER FBO PROJECTS TAGS: ABLD, KU
To: STATE

Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 06 JUL 2006